


Welding Shield Instruction Sheet

General Description

The Draeger Safety welding shield is designed to adapt to Panorama Nova P, Panorama RA and X-Plore series full face masks with stainless steel lens frames, without requiring modification to the mask. The welding shield utilizes flame resistant, self-extinguishing thermoplastics which have exceptional resistance to impact, heat, and welding splatter. Retaining clips hold the welding shield in place and eliminate the chance of the shield being dislodged. The welding shield is supplied with an impact-resistant cover lens. The large lift-front accepts standard $4\frac{1}{2} \times 5\frac{1}{4}$ filter plates.

Attachment

The welding shield is attached to the face mask by two retaining clips. Attach the shield to the mask with the Dräger logo toward the top of the mask. Attachment is best achieved by positioning one retaining clip at a time behind the lens frame. Once attached, the welding shield will be seated securely on the face mask.



USA
Draeger Safety, Inc.
101 Technology Drive
Pittsburgh, PA 15275
Tel 412 787 8383
Fax 412 787 2207

Customer Service
Tel 800 858 1737
Fax 800 922 5519

CANADA
Draeger Canada Ltd.
7555 Danbro Crescent
Mississauga, ON L5N 6P9
Tel 905 821 8988
Fax 905 821 2565

Customer Service
Tel 877 372 4371
Fax 800 329 8823

MEXICO
Draeger Safety S.A. de C.V.
Av. Peñuelas No. 5
Bodega No. 37
Fraccionamiento Industrial
San Pedrito
Querétaro, Qro. C.P. 76148
Tel +52 442 246 1113
Fax +52 442 246 1114

Customer Service
Tel 800 723 3891